

Antennas . Filters

Kathrein Inc., Scala Division

P.O. Box 4580

Medford, OR 97501 USA

Phone: 541-779-6500

Fax: 541-779-6575

mail@kathrein.com

www.kathrein-scala.com

July 30, 2010

Attn: Stephen Crissey, Consultant Bromo Communications, for

Voice Ministries of Farmington, Inc.

P. O. Box 232

Farmington, NM 87499

Email: Stephen@bromocom.com

Please Ref: **BNPFTB-20100608AIY**

KLJH-3 - Cortez, Colorado

Dear Mr. Crissey,

Thank you for your site elevation drawing and technical brief describing the proposed antenna installation for booster station KLJH on the same structure with translator directional antennas for stations K237CR and K300BN.

It appears the vertical antenna spacing as described in your brief along with the careful placement of your feed line will not cause any significant effect to the directional radiation patterns of stations K237CR and K300BN.

This opinion carries no performance guarantee and is based solely on the data provided by Voice Ministries of Farmington and the practical experience of our sales engineers. It is by no means a comprehensive analysis and Kathrein Inc., Scala Division recommends Voice Ministries of Farmington to engage the services of a qualified communications consulting firm for a definitive evaluation. The furnished data has not been verified by Kathrein Scala Division for completeness or accuracy.

If you need further assistance, please do not hesitate to contact me.

Best regards,

Michael Wm. Bach, Sales Engineer Kathrein Inc., Scala Division Email: mbach@kathrein.com

Ph: (541) 779 6500 Ext. 5128; Fx: (541) 779 3991

Direct: (541) 618 5128

MWB/jy

